



Official Consumer Food Protection Inspection Report

Department of Public Health Environmental Health Division
1221 Fulton Street, P.O. Box 11867, Fresno, CA 93775, Phone (559) 600-3357
<http://www.fcdph.org> Email: EnvironmentalHealth@fresnocountyca.gov

FACILITY ID: FA00277490	RECORD ID: FOOD00033322	CT: Tract 44.04
JACK'S MART 7264 N BLACKSTONE FRESNO CA 93650 LLC CALI ENTITIES	(559) 389-0573	Time In: 01/30/2026 10:30 am Time Out: 01/30/2026 12:00 pm Reinspection Date: 03/06/2026

FOOD Facility Final Inspection Permanent Food Facility - Market w/o Meat 1-500 Sq. Ft.

Permit Posted:	Permit Expiration Date: 04/30/2026	Balance Due: \$0.00
FSC Name:	Exp. Date:	Agency:
Linen (ppm) Cl:	Linen (ppm) Qt:	Utensil Sink (ppm) Cl:
Utensil Sink (ppm) Qt:	Hot Temperature:	Cold Temperature:

Violations / Not in compliance

TEMPERATURE CONTROL: Documentation required for all facilities with potentially hazardous food.		
Type of Food	Temp	Process/Holding Location

Observed and in Compliance:

General Comments:

THE FOLLOWING ITEMS NEED TO BE CORRECTED TO COMPLETE THE MINOR REMODEL PROCESS AND BE IN COMPLIANCE WITH THE CALIFORNIA RETAIL FOOD CODE:

1. RELOCATE OR PROVIDE A DIFFERENT 3-COMPARTMENT SINK TO ENSURE ALL LEGS ARE ON THE FLOOR SURFACE. TODAY 1 LEG (OF THE SINK) WAS POSITIONED ON THE CENTER OF A FLOOR SINK GRATE, WHICH IS NOT ALLOWED.
2. INSTALL SLIM FOOT COVE BASE IN THE WAREWASH ROOM AND AT THE TOE KICK SPACE OF THE SODA MACHINE CABINET. TODAY THE WAREWASH ROOM HAS FLAT TILE WITH A 90 DEGREE ANGLE, AND THE SODA MACHINE CABINET HAS RUBBER BASE; BOTH ARE NOT APPROVED.
3. PROVIDE SMOOTH VINYL CEILING TILES FOR THE WAREWASHING AREA AND RESTROOM. TODAY BOTH AREAS HAVE ACOUSTICAL CEILING TILES, WHICH ARE NOT APPROVED.
4. SEAL THE REMAINING WALL AREA BEHIND AND TO THE SIDE OF THE SODA MACHINE WITH FRP TO ELIMINATE ANY GAPS.
5. SEAL AROUND THE CEILING HOLE WHERE THE SODA LINES PASS THROUGH.
6. THE ICE MACHINE IS CURRENTLY INSTALLED IN FRONT OF A DOOR. PER OWNER, THE DOOR HAS BEEN CLOSED OFF FOR A WHILE. PROVIDE A WRITTEN DOCUMENT FROM THE LOCAL BUILDING DEPT. STATING THE DOOR CAN BE BLOCKED/SEALED TO C. DURAN. ICE MACHINE MAY NEED TO BE RELOCATED AND DRAIN TO A FLOOR SINK.
7. PROVIDE A PHOTO OF THE WATER HEATER CAPACITY TO C. DURAN. A MINIMUM WATER HEATER CAPACITY OF 40-GALLONS IS REQUIRED.

ONCE CORRECTIONS HAVE BEEN MADE, CALL C. DURAN FOR A REINSPECTION.

CLEARANCE TO USE THE BEVERAGE MACHINES WAS NOT GIVEN TODAY.

NOTICE: REINSPECTION FEES WILL BE CHARGED FOR REINSPECTIONS DUE TO UNCORRECTED VIOLATIONS

Received By: GUSTAVO, OWNER

Inspected By: Catherine Duran